


NOTICE TO THE CONSUMER

Your grill is equipped with a
Type II Quick Disconnect LP tank.



Bring the filler adapter to the filling station so the attendant can properly purge and fill your LP tank.



Filler Adapter

WHEN EXCHANGING YOUR LP TANK you must ensure the LP tank is equipped with a Type II Quick Disconnect connection.

ATTENTION!

IMPORTANT NEW FEATURES

Your Weber Gas Barbecue is equipped with a new and improved LP tank connection, that has additional safety features. They are:

1. The connection of the barbecue to the LP tank can be made without the use of tools.
2. The new connection will not permit the flow of gas until a positive gas connection is made.
3. If an accidental fire occurs at the LP tank connection, the flow of gas is stopped by a temperature activated shutoff.
4. If the LP supply hose becomes damaged, cut, punctured, or accidentally fire damaged, the barbecue connection is equipped with an excess flow control that will limit the flow of gas if leakage or a fire occurs.